

## 1998 Annual Report Review

Permittee: Andalex Resources, Inc.  
 Mine Name: Centennial Mines  
 Permit Number: ACT/007/019  
 Date Report Received 6/14/99  
 Assigned Reviewers: Jim Smith, Steve Demczak, Paul Baker

**Instructions:** The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the Mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine folder #6.

**Assignments: Inspectors:** Review cover sheet, AVS legal/financial, Mine sequence map  
**Hydrologists:** Review water monitoring data, Precipitation and climatological data, Non-coal waste  
**Biologists:** Review vegetation/revegetation success monitoring, Raptor survey  
**Engineers:** Review subsidence monitoring data, Annual impoundment certification, Annual overburden, spoils, refuse, floor, etc.

Section to review	Submitted Yes	No	Findings
Cover sheet	<u>X</u>	—	Complete as required
AVS; Legal/Financial Update	<u>X</u>	—	No changes reported
Mine Sequence Map	<u>X</u>	—	<u>Not</u> Certified, therefore not Complete, New maps to Jim Smith
Water Monitoring Data	<u>Yes</u>	—	No flow, no access, or negligible flow (no sampling) reported for all spring and stream sites, except 12-1 in Alrad Canyon is not reported at all. Sites 17-1 and 17-2 are reported but are not identified in the MRP. Well #1 is reported as sampled all four quarters, but there are no water level reports in DOGM's files: In fact, it appears DOGM has not received any quarterly reports from Centennial since 1996.